

19393 Cordelia Avenue Sonora, California 95370 **209/533-0567**

CERTIFICATE OF WARRANTY

Issued to: Oddfellow Sierra Park an incorporated community located in Tuolumne County, California. For: The interior coating of 220,000 gallon steel tank located and operated within the confines of the above development for potable water supply. Coating Type and Specification: CIM-1061 POTABLE WATER MEMBRANE applied in accordance with the manufacturer's recommendation.

THE ABOVE COATING IS UNDER WARRANTY FOR A PERIOD OF 18 YEARS BEGINNING ON OCTOBER 6, 1998 AND ENDING OCTOBER 5, 2016 AS INDICATED ON INVOICE #98-601 DATED OCTOBER 6, 1998.

THE WARRANTY COVERS: ANY DELAMINATION OF COATING THAT MAY OCCUR IN THIS PERIOD. (peeling, chipping, flaking or hydrodigesing) It is up to the owners to keep the exterior in good condition to prevent rust through on roof. Underneath the floor is an unknown and is not implied in this

warranty-only delamination or rusting that originates within the vessel is covered.

Porter/Cal-Western Inc. agrees to maintain any damage resulting from above (excluding items not covered) in a timely manner without cost to Oddfellows Sierra Park.

Discoloration due to rust found naturally in the well water can stain interior coating and does not necessarily indicate rusting of the steel. It also rarely involves more that the superficial surface and causes no damage.

The above warranty applies to the original contract #98-007 on file.

We agree to the above warranty

Porter/Cal-Western Inc.

Ross Porter-CEO

Date: 12/12/98