

DDFELLOW SIERRA PARK		SCURCE	SPRING WELL		MONTH	YEAR	TANK LEVEL	REMARKS
	METER READING	GALLONS	CHLORINE	PH	GPM			
6	36777700							
7	36789700							
8	36801900							
9	36818100							
		40400						
PUMPED SPRING WELL ON DATES INDICATED, TO CHLORINATE SYSTEM.								
JTB								

